

Tickets

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
628	Biwak	Feature	Neu	Normal	use 128 bit UID	Maximilian Seesslen	28.03.2025 16:45
625	CANHub	Feature	Neu	Normal	Add websocket server	Maximilian Seesslen	18.03.2025 17:40
624	CANHub	Feature	Neu	Normal	Bring it github	Maximilian Seesslen	18.03.2025 17:03
622	pics	Fehler	Neu	Normal	pic2		13.03.2025 20:25
621	pics	Fehler	Neu	Normal	bilder		13.03.2025 20:19
619	mainSwitch	Fehler	Neu	Normal	LM25056: Current calculated wrongly		11.03.2025 15:37
615	mainSwitch	Feature	Neu	Normal	Verseion 2: more power, RTC		28.02.2025 11:44
614	Squeezer	Fehler	Neu	Normal	Errors are not handled reliable		03.03.2025 16:39
611	libcampo	Feature	Neu	Normal	Bringup:	Maximilian Seesslen	17.02.2025 18:36
608	Mainswitch	Feature	Neu	Normal	Shutdown command	Maximilian Seesslen	29.01.2025 16:57
603	libcampo	Feature	Neu	Normal	Vagus: CAN: use filters	Maximilian Seesslen	22.01.2025 14:24
595	Kokon	Feature	Neu	Normal	Check board id and revision before flashing	Maximilian Seesslen	15.01.2025 15:12
593	libcampo	Feature	Neu	Normal	hwdata: clean up	Maximilian Seesslen	13.01.2025 15:38
591	Biwak	Feature	Neu	Normal	move timing functions to systimer.cpp	Maximilian Seesslen	15.01.2025 11:54
587	Squeezer	Feature	Neu	Normal	Readme is missing	Maximilian Seesslen	18.12.2024 13:54
586	Biwak	Feature	Neu	Normal	Test implementation of eventLoop class	Maximilian Seesslen	27.11.2024 13:55
583	fosh	Fehler	Neu	Normal	When too much commands are added, no command is available	Maximilian Seesslen	12.11.2024 16:49
582	CANDis	Feature	Neu	Normal	change TDT command to set/get time/date to time_t	Maximilian Seesslen	12.11.2024 16:13
581	CANRec	Feature	Neu	Normal	replay only newer data	Maximilian Seesslen	12.11.2024 11:38
580	CANRec	Feature	Neu	Normal	add command to erase older data	Maximilian Seesslen	12.11.2024 11:39
579	TCB	Feature	Neu	Normal	Generate list of packages	Maximilian Seesslen	11.11.2024 10:57
578	TCB	Fehler	Neu	Normal	Python from host is involved	Maximilian Seesslen	11.11.2024 10:55
577	TCB	Fehler	Neu	Hoch	Not all binaries get patched to use own interpreter	Maximilian Seesslen	11.11.2024 14:48
575	Biwak	Feature	Neu	Normal	Implement function to configure OSC with HSI only	Maximilian Seesslen	27.11.2024 13:51
567	Biwak	Feature	Neu	Normal	Clean up heart-beat-LED-code		25.09.2024 13:59
566	theme_noto	Feature	Neu	Normal	create const icon references	Maximilian Seesslen	09.01.2025 16:06
558	CANDis	Fehler	Neu	Normal	Reading touch calibration is very unreliable	Maximilian Seesslen	07.10.2024 14:50
557	CANDis	Fehler	Neu	Normal	When switchin from "minutnik running items" to clock, background of letters are violet	Maximilian Seesslen	27.08.2024 22:41
553	CANHub	Feature	Neu	Normal	implement monitor mode	Maximilian Seesslen	23.08.2024 13:23
552	CANHub	Feature	Neu	Normal	Implement Heartbeat	Maximilian Seesslen	23.08.2024 13:42
550	TDTPrompt	Feature	Neu	Normal	Show CANHub connector status on status bar	Maximilian Seesslen	20.08.2024 15:07

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
547	CANHub	Feature	Neu	Normal	Loop detection	Maximilian Seesslen	15.08.2024 16:12
546	CANHub	Feature	Neu	Normal	multiple servers	Maximilian Seesslen	15.08.2024 16:01
544	CANHub	Fehler	Neu	Normal	Connectors: tolerate wrong sizes	Maximilian Seesslen	15.08.2024 15:23
517	Sensemux SW	Feature	Neu	Normal	Why does mainswitch stabilize values?		24.04.2024 12:08
514	CANSwitch	Feature	Neu	Normal	Test arena generated handler structure	Maximilian Seesslen	05.02.2025 16:30
511	Mainswitch	Requirement	Neu	Normal	An keep-awake-event via CAN should extend shutdown timeout	Maximilian Seesslen	06.09.2024 11:22
510	Mainswitch	Requirement	Neu	Normal	timeout shutdown	Maximilian Seesslen	06.09.2024 11:19
501	CANSwitch	Test	Neu	Normal	Send wanna-sleep		17.04.2024 18:22
497	libcampo	Feature	Neu	Normal	campo.sh: add changeLogSubmodules	Maximilian Seesslen	26.02.2024 18:31
495	Minutnik elnk	Unterstützung	Neu	Normal	Are both wakeups working correctly	Maximilian Seesslen	23.02.2024 13:22
494	Minutnik elnk	Unterstützung	Neu	Normal	Does UART-RX need Pullu por -down?	Maximilian Seesslen	23.02.2024 13:21
489	CANSwitch	Test	Neu	Normal	Send keep-alive	Maximilian Seesslen	17.04.2024 18:22
488	CANSwitch	Test	Neu	Normal	Fading out before timeout	Maximilian Seesslen	17.04.2024 18:22
486	CANSwitch	Test	In Bearbeitung	Normal	timeout warning	Maximilian Seesslen	11.02.2024 07:43
474	campoTemplate	Fehler	Neu	Normal	Git history is not reset	Maximilian Seesslen	19.01.2024 17:47
473	campoTemplate	Fehler	Neu	Normal	There is no actual template for README.md		19.01.2024 15:21
471	mainSwitch	Fehler	Neu	Niedrig	Wakeup-Button is not working	Maximilian Seesslen	05.02.2024 22:54
464	CANRec	Fehler	Neu	Normal	time zones are not handled at all	Maximilian Seesslen	12.11.2024 14:53
463	Canbridge	Feature	Neu	Normal	support bootcounter in config	Maximilian Seesslen	27.12.2023 17:12
454	Rufa	Feature	Neu	Normal	Verify smoothener		12.12.2023 16:55
450	liblepto	Feature	Neu	Normal	CRing: the m_top/m_bottom concept wastes one entry		05.06.2024 14:02
443	Mito	Feature	Neu	Normal	implement validate mode	Maximilian Seesslen	20.11.2023 15:54
442	Canbridge	Feature	Neu	Normal	Use listening mode	Maximilian Seesslen	20.11.2023 15:32
441	Canbridge	Feature	Neu	Normal	Measure current consumption in RX mode	Maximilian Seesslen	20.11.2023 15:31
439	Canbridge	Fehler	Neu	Normal	Check RSSI instead of delaying	Maximilian Seesslen	20.11.2023 15:05
435	mainSwitch	Fehler	Neu	Normal	Power supply on CANBus is very poor		14.11.2023 14:48
431	Rufa	Feature	Neu	Normal	Introduce more noise filtering		06.11.2023 16:47
429	Canbridge	Feature	Neu	Normal	Multi-Nodes	Maximilian Seesslen	20.11.2023 15:10
428	Canbridge	Feature	Neu	Normal	Retransmit Messages	Maximilian Seesslen	27.10.2023 13:26
426	Rufa	Fehler	Neu	Normal	Footprint fuer thermocouple-Kupplung hat fehler	Maximilian Seesslen	15.09.2023 11:28
425	Cablemeter	Feature	Neu	Normal	PCB: missing info for 3V	Maximilian Seesslen	12.09.2023 12:03
421	CANBuz	Feature	Neu	Normal	Create sinewave for DAC/DMA	Maximilian Seesslen	28.08.2023 18:52
420	libscapus	Feature	Neu	Normal	bme680: calculate absolute humidity	Maximilian Seesslen	14.08.2023 15:04

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
418	libcampo	Feature	Neu	Normal	campo.sh: verify "release" function	Maximilian Seesslen	20.07.2023 14:19
416	MWidgets	Feature	Neu	Normal	CPlotter: show date when time range is too big	Maximilian Seesslen	13.07.2023 16:12
388	NUC64DEBUG	Feature	Neu	Normal	use bigger buttons	Maximilian Seesslen	27.03.2023 14:24
369	CANIO	Feature	Neu	Normal	Send alarm on I2C error	Maximilian Seesslen	01.03.2023 11:43
365	Cordyceps	Feature	Neu	Normal	Show event marker in plots	Maximilian Seesslen	13.07.2023 13:55
364	Sensemux SW	Feature	Neu	Normal	evaluate more values	Maximilian Seesslen	13.02.2023 17:28
363	Cordyceps	Feature	Neu	Normal	Show marker in plots	Maximilian Seesslen	11.07.2023 16:36
357	TCB	Fehler	Neu	Normal	python-host: on debian pip and setuptools are not created automatically	Maximilian Seesslen	02.02.2023 14:31
355	TCB	Feature	Neu	Normal	activate chroot tests again	Maximilian Seesslen	22.05.2024 10:33
354	TCB	Fehler	Neu	Normal	autoconf directory from host is used	Maximilian Seesslen	02.02.2023 11:40
350	fosh	Feature	Neu	Normal	implement generic subcommands	Maximilian Seesslen	24.01.2023 18:23
349	Mainswitch	Requirement	Neu	Normal	Low voltage alert	Maximilian Seesslen	06.09.2024 11:19
345	libcampo	Feature	Neu	Normal	unit tests: parse hwinfo files	Maximilian Seesslen	28.11.2023 14:15
342	CANDis	Feature	Neu	Normal	USB CDC tester	Maximilian Seesslen	02.02.2023 11:56
327	Minutnik elnk	Fehler	Neu	Normal	Power consumption too high	Maximilian Seesslen	09.01.2023 13:26
317	PhonyBL	Feature	Neu	Normal	Implement big Statemachine	Maximilian Seesslen	21.11.2022 13:41
311	Biwak	Feature	Neu	Normal	Implement DMA USB	Maximilian Seesslen	14.11.2022 11:08
290	Minutnik elnk	Fehler	Neu	Normal	Yellow and red LEDs are quite dark	Maximilian Seesslen	26.10.2022 14:38
271	Minutnik elnk	Fehler	Neu	Normal	consumption tests completely missing	Maximilian Seesslen	14.10.2022 15:57
270	Minutnik elnk	Feature	Neu	Normal	Font in SPI-Flash	Maximilian Seesslen	29.11.2022 10:12
248	miniminutnik	Fehler	Neu	Normal	hw v0.2.x: add quirk to board file for UART pulldown	Maximilian Seesslen	14.08.2023 12:36
242	libocelli	Feature	Neu	Normal	implement png reader	Maximilian Seesslen	12.01.2023 19:00
241	Biwak	Feature	Neu	Normal	implement SPI DMA transmit	Maximilian Seesslen	30.01.2023 10:28
233	mainSwitch	Feature	Neu	Normal	Switch via photodiode	Maximilian Seesslen	11.12.2022 17:39
210	mainSwitch	Fehler	Neu	Normal	PCB routing problem	Maximilian Seesslen	01.02.2024 14:27
187	sensemux	Unterstützung	Neu	Normal	Bringup HW v0.2.x	Maximilian Seesslen	24.01.2023 13:59
186	Sensemux SW	Fehler	Neu	Normal	RTC does not store date	Maximilian Seesslen	13.02.2023 17:17
185	CANDis	Feature	Neu	Niedrig	Evaluate RTC calibration	Maximilian Seesslen	02.02.2023 13:12
176	Campo	Feature	Neu	Normal	create custom targets to cmake file to create and deploy documents	Maximilian Seesslen	27.06.2022 18:23
144	Campo	Feature	Neu	Normal	implement hwdata stterm command		24.11.2023 14:38
135	Hardware	Unterstützung	Neu	Normal	Create BOM creator script with warehouse fields	Maximilian Seesslen	13.01.2022 15:30
75	libcampo	Unterstützung	Neu	Normal	bringup: Create test to write internal flash	Maximilian Seesslen	19.12.2023 16:49
32	Hardware	Fehler	Neu	Normal	Move the notes from "warehouse" to redmine.	Maximilian Seesslen	13.08.2021 12:56

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
31	NUC64DEBUG	Fehler	Neu	Niedrig	BOOT0 Button pulls pin low instead of high		13.08.2021 12:56
13	Minutnik	Fehler	Neu	Normal	Buttons do not fit		17.08.2021 13:24