

Minutnik

		2026-1					2026-2					2026-3					2026-4					2026-5					2026-6				
		2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26					
Hardware																															
Minutnik																															
Buttons do not fit																															
Minutnik elnk																															
Does UART-RX need Pullu por -down?																															
Minutnik elnk - v0.2.x																															
consumption tests completely (...)																															
Yellow and red LEDs are quite (...)																															
Power consumption too high																															
Are both wakeups working correctly																															